

Customer Name

Inspection Dates


SAMPLE REPORT

MACHINERY VIBRATION REPORT

EQUIPMENT NAME	PROBLEM DESCRIPTION	PRIORITY
Primary Conveyor Gravity Takeup, Upper Bend Roll	Continue to note possible wear in spectral data of non-drive end upper bend bearing / roll. Impacting remains in time waveform data at shaft speed. See attachment for waterfall of time waveform.	Med-High

RECOMMENDED ACTION: Check shaft and roll for possible cracks / fatigue, bearing should be checked for excessive clearance / wear.

Problem Found / Action Taken	Bushing broke. Changed bushing.
------------------------------	---------------------------------



“Your Partners in Pro-Active Maintenance”