

THERMOGRAPHIC REPORT

Company | XYZ

Problem # |

IDENTIFICATION


Location Name | Location 8

Equipment | Machine #64

PROBLEM DESCRIPTION

Siemens contact block in bottom left of disconnect panel is hot.

THERMOGRAM



TEMPERATURE MEASUREMENTS

Image Date	8/28/2007 11:22:28 PM
Target Temperature	116.5 °F
Emissivity	0.99
Reflected Temp	OFF

WEATHER

Air Temp	NA
Sky	NA
Wind Speed	NA
From	NA

Distance	Rated Load	Meas. Load	% Load
NA	NA	NA	NA

MAINTENANCE ACTION

Description	Repaired by
Possible loose lead. Ensure tight connection.	

REPAIR PRIORITY **Med-High**

Subj. Rating

Temp. Rating

REINSPECTION

Reinspected by

Date



Comments

THERMOGRAPHIC REPORT

Company | XYZ

Problem # |

IDENTIFICATION


Location Name | Location 6

Equipment | Machine #53

PROBLEM DESCRIPTION

Clutch #91 relay is hot.

THERMOGRAM



TEMPERATURE MEASUREMENTS

Image Date	8/28/2007 4:44:15 AM
Target Temperature	107.1 °F
Emissivity	0.94
Reflected Temp	OFF

WEATHER

Air Temp	NA
Sky	NA
Wind Speed	NA
From	NA

Distance	Rated Load	Meas. Load	% Load
NA	NA	NA	NA

MAINTENANCE ACTION

Description	Repaired by
Possible defective relay. Replace relay.	

REPAIR PRIORITY **Med-High**

Subj. Rating |

Temp. Rating |

REINSPECTION

Reinspected by |

Date |



Comments