

MACHINERY VIBRATION REPORT

EQUIPMENT NAME	PROBLEM DESCRIPTION	PRIORITY
Conveyor #12	HFD and acceleration levels have trended up sharply on the drive side tail pulley bearing. Potential rub or worn bearing.	Med-High
RECOMMENDED ACTION:	Inspect drive side tail pulley bearing for rubbing or bearing wear. Repair based on inspection results.	

<i>Problem Found / Action Taken</i>

