

Customer Name

Inspection Dates

# SAMPLE REPORT


## MACHINERY VIBRATION REPORT

EQUIPMENT NAME	PROBLEM DESCRIPTION	PRIORITY
----------------	---------------------	----------

<b>Conveyor 22 (10000122)</b>	HFD levels continue to trend upward at output of gearbox, vibration at suspected gearmeshing frequency of the output gearset continues to increase. Suspect extensive wear in output gearset. See attachment for waterfall spectral plot. <b>No current oil sample noted online.</b>	<b>High</b>
-----------------------------------	--	-------------

RECOMMENDED ACTION: Replace / recondition gearbox promptly.

<i>Problem Found / Action Taken</i>	Broken tooth / wear on pinion of output gearset.
-------------------------------------	--



*"Your Partners in Pro-Active Maintenance"*