MDI *Machine Diagnostics, Inc.*

XYZ Corporation
Anywhere, USA

Inspection Date
M/D/Y

MACHINERY VIBRATION REPORT

EQUIPMENT NAME	PROBLEM DESCRIPTION	PRIORITY
CHP-1	HFD levels are excessive in pump; spectral data reveals significant looseness / wear.	**Med-High**
RECOMMENDED ACTION:	Ensure pump bearings are properly lubricated. Pump should be replaced / reconditioned within 30 day time frame.	
Action Taken; Problem Found		



"Your Partners in Pro-Active Maintenance"