

MACHINERY VIBRATION REPORT

EQUIPMENT NAME	PROBLEM DESCRIPTION	PRIORITY
Dry Ducon Fan	Unbalance is trending upward in fan.	Medium
RECOMMENDED ACTION: Inspect fan rotor for wear and possible buildup of parasitic debris. Unit should be considered for dynamic balancing.		

Problem Found / Action Taken

