

The spectrum above shows harmonics of this bearings outer race defect frequency at 1125 RPM. These frequencies were produced by a defect 8 inches long and $1\frac{1}{2}$ inches wide.



The defects can be seen in this photo at the bottom of the outer race.

Is your plant utilizing this powerful PdM tool to detect potential failures such as this?



